

## EAA Flight Advisor

WHEN THE PILOT OF A NEWLY completed airplane contacts me for Flight Advisor assistance, I follow EAA guidelines to evaluate his or her skills and carefully prepare the pilot for the first few flights. Then I explain that once the airplane has been successfully flown, he is actually *beginning* a development phase of flight-testing to identify and continuously solve problems until the airplane operates problem free. It's essentially the same process that aircraft manufacturers follow before their airplanes are delivered to customers.

The "perfect" airplane is rarely produced. Unlike factory-built cars and trucks, amateur-built aircraft are not built with high-tech automation. A large portion of the work is still done with human hands, and to make matters more complex, each customer has different requirements (product improvement) and skills.

# Development Flight Testing

Using a team approach to work out the bugs

TERRY LUTZ



From a production run of 4,077 F-16s for 18 different air forces around the world, for instance, Lockheed-Martin has produced only 10 "perfect" airplanes. That means that a company test pilot flies it and finds no discrepancies, and then an air force test pilot flies it and finds

no discrepancies. Next, the air force maintenance team at the factory tears it apart and inspects every nut, clamp, wire bundle, hydraulic line, and every other imaginable maintenance item. (Remember that the next time you change washers under an AN-3A bolt to get one-and-one-half threads to show.) If no problems are found, an air force delivery pilot ferries the airplane to the gaining unit. If there are no maintenance write-ups on arrival, the "perfect" status remains intact. Finally, the maintenance organization of the gaining unit tears the F-16 apart, and once again every last detail is checked. If no discrepancies are found, it's one of those rare, "perfect" airplanes.

Comments about the first flight of a new homebuilt or restoration project often read, "It was in perfect trim and flew hands off." What you don't hear about is the tail wheel shimmy, substantial air leak around




Carl Franz assisting Ted Gauthier with the Grand Rapids Technologies EIS settings.



Ted Gauthier's RV-6 during an engine run prior to first flight.



Chase pilot Lou Farhood gets ready to strap into his RV-8 before the first flight.



Ted Gauthier taking a lot of screws out to remove the leaking fuel tank.

the door, or the fuel streaking around one of the vents.

Knowing that your airplane is entering a development phase, what can you do to identify and resolve the discrepancies that are bound to appear? Ted Gauthier, a member of EAA Chapter 1056, in Fowlerville, Michigan, recently completed a dazzling RV-6. Power comes from a Superior SL-360 engine with a fixed-pitch prop that has a spectacular checkerboard paint design. The full gyro panel houses a Grand Rapids Technologies EIS and a lift reserve indicator. A Garmin GPS III is carefully flush-mounted in the panel, but the real navigation tool is a Compaq iPaq PDA with a color-moving map driven by Anywhere Map software. The software also has an Excel spreadsheet that automatically calculates gross weight and center of gravity from pilot inputs.

Gauthier and three other home-builders—Lou Farhood, RV-8, Chapters 1056 and 55; Carl Franz, RV-6, Chapter 1056; and me, RV-8, Flight Advisor, Chapter 55—used a team approach to resolve all the discrepancies that appeared during the first 40 hours of flight. Each of us had a specific responsibility. Gauthier had the total project perspective and shared the test flying. We expressed our technical con-

## VISION BEYOND SIGHT.



Actual approach into Telluride, Colorado.

Close your eyes and imagine a device that erases weather and darkness, making every flight sunny VFR.

Imagine a device that makes the most complicated instrument approaches so easy that a child can fly them.

Imagine a device that can eliminate 85% of all general aviation accidents.

Imagine a device that can instantly tell you anything you need to know about your flight, like a robot copilot that never blinks.

Imagine a device so advanced that it has actually been purchased by NASA and the FAA.

Now imagine all this from a stable, multi-billion dollar company that has been in business for over 50 years.

Open your eyes to the Sierra EFIS-SV, the world's only synthetic vision flight display, because there's more out there than meets the eye.

**CHELTON**  
FLIGHT SYSTEMS

www.cheltonflightsystems.com

Call (208) 389-9959 for more information today.


©2002 Chelton Flight Systems, Inc.

# Welds That'll Fly By Any Inspection



HTP lets you get precise, professional results on any critical aircraft weld.

Our Invertig 200 AC/DC TIG welder puts 200 amps of power in an affordable, compact, package, yet pulls only 25 amps so you don't have to re-wire your shop. It's also produces 10% more welding current while using 60% less electricity.




- A standard pulser makes welding thin aluminum and steel easier
- Adjustable AC frequency means greater control over the arc
- AC balance adjusts from 10% to 90%, allowing greater penetration or cleaning

HTP is your source for Migs, TIGs, Auto-Darkening Helmets and Supplies. Call 1-800-USA-WELD for info or our Free 48-Page Catalog.

**HTP** America Inc.

3200 Nordic Rd, Arlington Hts, IL 60005  
www.usaweld.com

EAA03



## Everything that keeps you flying



In print. Online.  
Subscribe today.

**Trade-A-Plane**

The Aviation MarketPlace  
800.337.5263 • 931.484.5137  
www.trade-a-plane.com

SPA

For more information, visit SPORT AVIATION on the Web at [www.eaa.org](http://www.eaa.org)

## EAA Flight Advisor

cerns to him, and he provided the construction background and the hands-on to resolve problems before the next flight. Farhood assisted with assembly details, made parts as required, and flew as chase pilot. Franz was the expert on wiring, integration, and programming of the electronic systems, and he shared the test flying. I did the test planning, data reduction, and a portion of the test flying. And we all helped each other, as spare time permitted.

So how did it go? What did we find? There were some comm problems on the first flight—no loss of radios—but there was a persistent problem that we traced to a bad ground at the microphone jack on the pilot's side. We also had a significant airspeed error, which Farhood identified from the chase RV-8 during a practice approach at altitude. There were numerous warnings from the EIS because the EGT limit was set too low. We were unable to display manifold pressure and fuel flow on the EIS. Cold air flowed from a large air leak at the back of the canopy, the transponder was not reporting Mode C, and there was a mild roll-off to the left at cruise speed. No, it was not a "perfect" flight, but we had a plan to identify and solve the

problems that popped up.

### Problem Solving

Over the course of 40 hours of Phase I testing (Gauthier's RV has an uncertified engine/prop combination), we developed a "Top 5" list of problems that had to be solved:

**Fuel Leak:** The airplane was topped off just before the first flight, and we noticed a fuel seep from stains on the underside of the wing along the spar. Over the course of testing, we removed the tank twice to find the leak. It finally took a pressure test and a complete cleaning and pro-sealing of the tank seam to cure it.

**Airspeed Error:** Our chase airplane confirmed that a significant airspeed error existed. Early GPS runs confirmed it, and clean stalls were occurring at 45 mph indicated airspeed, which was a bit slower than expected. Gauthier took the airspeed system apart and found that an O-ring was missing on the pitot connection at the airspeed indicator. Replacing the O-ring, however, did not correct the problem.

We did a complete airspeed calibration using a method developed by Greg Lewis at the National Test Pilot School. (The spreadsheet can be downloaded free from their web-

<u>IAS in knots</u>	<u>dVpc (source at pitot)</u>	<u>dVpc (source at fuselage)</u>
50	7.7	-1.3
60	4.6	-1.3
70	3.2	-1.6
80	0.0	-1.0
90	-2.0	-1.1
100	-5.1	-1.6
110	-6.6	-2.6
120	-5.4	-1.3
130	-6.6	1.1
140	-8.8	0.6
150	-9.2	-0.4
160	-11.3	0.0

Airspeed calibration table

site at [www.ntps.edu/downloads.htm](http://www.ntps.edu/downloads.htm).) Gauthier had installed a heated pitot tube that had pitot and static sources. He switched the source of static air from the pitot tube to ports mounted on either side of the fuselage, with great results. From the table on the left, you can see that at a cruise speed of 160 knots, the error is actually 0.0 knots.


**Pitch Trim:** Even though we had enough nose-up and nose-down trim, our sharp-eyed chase pilot pointed out that there was significant trim-tab deflection at cruise.

*The team approach may not work for everyone, but the value of extra eyes, extra experience, and expertise cannot be understated.*

Gauthier added two 3/32-inch shims under the horizontal tail, and adjusted the travel of the Mac trim servo. After a few more flights, one more shim was added, and the tab is now at zero deflection at cruise, with a full range of trim available.

**EIS Programming:** After the problems were noted on the first flight, Franz tackled the job of verifying all the parameters on the EIS, and customized the pages that we wanted to fly with, particularly for the engine break-in period. The one remaining issue was to accurately calibrate the fuel-flow system, which Franz accomplished over a couple of flights.

**Engine-Baffle Adjustments:** Flight-testing indicated that the forward two cylinders were consistent-



**You Can Build It!  
Let EAA Teach You How.**

EAA SportAir Sponsors

[www.polyfiber.com](http://www.polyfiber.com) [www.aircraftspruce.com](http://www.aircraftspruce.com)



**EAA SPORTAIR WORKSHOPS**

1-800-WORKSHOP  
1-800-967-5746  
[sportair@eaa.org](mailto:sportair@eaa.org)


Visit [www.sportair.com](http://www.sportair.com)  
for a complete listing of workshops.

**Workshop Schedule**

- Aug 23, 2003 Arlington, WA  
TEST FLYING YOUR PROJECT
- Aug 23-24, 2003 Arlington, WA  
SHEET METAL BASICS  
COMPOSITE CONSTRUCTION  
FABRIC COVERING  
ELECTRICAL SYSTEMS  
& AVIONICS
- Sept 5-7, 2003 Griffin (Atlanta), GA  
TIG WELDING
- Sept 12-14, 2003 Corona, CA  
RV ASSEMBLY
- Sept 20, 2003 Denver, CO  
TEST FLYING YOUR PROJECT
- Sept 20-21, 2003 Denver, CO  
SHEET METAL BASICS  
COMPOSITE CONSTRUCTION  
FABRIC COVERING  
ELECTRICAL SYSTEMS  
& AVIONICS  
INTRO TO AIRCRAFT BUILDING
- Sept 26-28, 2003 Griffin (Atlanta), GA  
RV ASSEMBLY
- Oct 4-5, 2003 Columbus, OH  
SHEET METAL BASICS  
COMPOSITE CONSTRUCTION  
FABRIC COVERING  
ELECTRICAL SYSTEMS  
& AVIONICS  
GAS WELDING
- Oct 10-12, 2003 Oshkosh, WI  
RV ASSEMBLY

ly operating cooler than the aft two, so Gauthier and Franz increased the baffle height at the front of the engine. It took a couple of adjustments to get the cylinder head temps all about the same. Some changes were also made to the baffle seals above the oil cooler and at the carburetor air inlet.

**One Important Item:** There were no problems with the SL-360 engine. From the first engine run



Terry Lutz with the RV grin after flying Ted Gauthier's RV-6.

## EAA's Member Specials

### BLACK TOTE

E41198

Nylon tote with blue Member logo. Keep organized while showing your EAA pride.

**Member Price: \$10.99**

**Non-Member Price: \$14.99**

### STEEL BLUE SWEATSHIRT

E41194

Lee® premium cotton/polyester blend sweatshirt featuring the EAA Member Logo.

**Member Price: \$34.99\***

**Non-Member Price: \$39.99\***

Add \$4 for 2XL



Order Online [www.eaa.org](http://www.eaa.org)

Telephone Orders **800-843-3612**  
From US and Canada (All Others Call 920-426-5912)

EAA Mail Orders  
P.O. Box 3086

Oshkosh, WI 54903-3086

Please present EAA number and product code when ordering. Prices effective August 1 - November 30, 2003. Major credit cards accepted. WI residents add 5% sales tax. Shipping and handling NOT included.



The Leader In Recreational Aviation

For more information, visit SPORT AVIATION on the Web at [www.eaa.org](http://www.eaa.org)

and throughout Phase I testing, it has operated trouble free. During the engine build-up, Gauthier again used the team approach. Ron Cooper (Cooper Air Repair, EAA Chapter 1056) provided the technical expertise during engine assembly, and hands-on assistance with fittings, hose placement, and control rigging.

Altogether, Gauthier had the cowl off 22 times in 40 hours of flying, and he removed the floor panels seven times to check wiring, aileron trim, and the flight controls. We often think that the most intense period during construction is when we are attending to a million details before the first flight. But unless you build the "perfect" airplane, that simply isn't so. Solving the problems identified in Phase I testing can be equally intense. The experience we had with Gauthier's airplane is an example of how important it is to properly conduct development testing after the first flight. The team approach may not work for everyone, but the value of extra eyes, extra experience, and expertise cannot be understated. The result: a superb airplane that will give Ted Gauthier many hours of trouble-free flying whenever he wants to strap it on and go.

*Flight Advisor Terry Lutz is a former Air Force pilot and graduate from the USAF Test Pilot School. He evaluates large transport aircraft and systems for the Air Line Pilots Association, flies the DC-9 at Northwest Airlines, and can't wait to finish his RV-8.*

